


07.06.2016 by Daniel Kofler

Safety notice for harnesses equipped with Finsterwalder



SWING would like to refer to a current safety message from Finsterwalder:

<http://www.dlv.de/dl/1/source/technicalstatepertnotes.php?lang=en&item=245f>

There are exclusively harnesses affected that are equipped with CLICK-LOCK® (HS10) or T-LOCK® in the chest strap! SWING is about to clarify with the suppliers which models of SWING harnesses might be affected and if a restriction of special serial numbers could be realized. Affected clients can always check the current status of information and possible solutions on the SWING homepage and on the SWING Facebook fan site. We ask for understanding that we have to make an assessment of the situation at the very first before deciding about the way of proceeding