


06.08.2014 by Daniel Kofler

Safety message from Woody Valley



SWING would like to refer to a current safety message from Woody Valley:

[Download \(pdf Document attached\)](#)

Only the harness models Connect RACE and Connect REVERSE EVO may be affected. Only on those harnesses the affected buckles (slim, red with WV engraving) are used for the chest / legstrap. We ask all owners of the above harnesses to perform the closing test as described and if found faulty to contact Woody Valley directly for a repair.

WOODY VALLEY s.r.l.

Tel.: [+39.0461.950811](tel:+39.0461.950811) - Fax: [+39.0461.950819](tel:+39.0461.950819)

info@woodyvalley.com